


ILLEGIBLE

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office San Antonio  
Lease No. 82-071128  
Unit 129



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 23, 1959

Well No. 7 is located 700 ft. from S line and 1000 ft. from E line of sec. 12


8/55 Section 12 (1/4 Sec. and Sec. No.)  
1-21-1 (Twp.)  
1-21-1 (Range)  
1-21-1 (Meridian)  
San Antonio (Field)  
San Antonio (County or Subdivision)  
San Antonio (State or Territory)

The elevation of the derrick floor above sea level is 2000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth - 2710'. 2710' - 2717' - perforated fractured bluffs formation - 3/75-76, 250-22, 2723-24 with two (2) shots per foot. sand-water trapped 3/22/59 with 700 lbs. water and 50,000 sand - Breakdown pressure - 2000', breathing pressure - 1500', standing pressure - 1000' i.h. - 14 bps. Limited 2726' (10' i.h.) of 1" tubing at 2710'. Shut in for cause.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San Antonio

Address San Antonio, Texas

By Joe C. Salmon

Title District Supervisor