


ILLEGIBLE



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budget Bureau No. 42-E358.4.
Approval expires 12-31-60.

Land Office _____
Lease No. _____
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	✓
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 21, 1959


Well No. 7 is located 200 ft. from [N] line and 150 ft. from [E] line of sec. 12
 12 (Sec. and Sec. No.) 11 (Twp.) 11 (Range) 11 (Meridian)
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 521 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

total depth = 2700'. an logs = top of fractured Clinton formation at 275'.
 set 43 joints, 7/22.25' of 1 1/2" casing at 2690' with 50 sacks cement. filled
 cement plug 1/21/59. cleaned out to 2620'. has had hole try, tested for
 2 hours with 500' pressure - pipe okay.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company _____

Address _____

By _____

Title _____