


ILLEGIBLE

(SUBMIT IN TRIPLICATE)

Land Office Santa FeLease No. 078190Unit 150UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 24, 19 60Well No. 6 is located 1550 ft. from S line and 1150 ft. from W line of sec. 12QNG, Sec. 12
(1/4 Sec. and Sec. No.)T-50N
(Twp.)R-11W
(Range)N.M.P.M.
(Meridian)Astec, Pictured Cliffs
(Field)San Juan
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 5023 ft. (G.L.)**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded 2/23/60

Set 97' of 7 5/8" surface casing, landed at 103' with 100 sacks cement

Tested Casing with 500# pressure, for 30 minutes. No leaks.

Drilled cement plug 2/24/60

Tested Casing with 500# pressure for 30 minutes.

Pipe okay.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Astec Oil & Gas CompanyAddress Box # 786,Farrington, New Mexico

ORIGINAL SIGNED BY JOE C. SALMON

By Joe C. SalmonTitle District Superintendent

