


Santa Fe

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office 078336  
Lease No. W/2 Sec. 11  
Unit \_\_\_\_\_



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	X	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 22

Well No. 18 is located 1650 ft. from N line and 990 ft. from E line of sec. 11  
SW/4, Sec. 11 30-N 9-W NMPM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Blanco Mesaverde San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6076 ft. G. L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Kill well, pull tubing. Run 7" retrievable packer on tubing, set at approximately 4400 and swab well in. This is a temporary measure to evaluate well for workover possibilities.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations are commenced.

Company Delhi-Taylor Oil Corporation

Address Drewer 1198

Parmington, New Mexico

Original signed by  
By G. T. HIGGINBOTHAM  
G. T. Higginbotham  
Title District Superintendent