## NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103 (Rev 3-55)

## MISCELLANEOUS REPORTS ON WELLS

		Submit to appropr	iate Districi	Office as	per Con	mission R	ule 1106)		
Name of Con Delh	i-Tayler Cil C	orporation		Addre P. (	ss Bex	1198, F	armington,	New Mex	cice
Lease Flor	ance	4	Vell No.	Unit Letter	Section	Township	,	Range 9-	-W
Date Work Performed Pool Mesaverde				•	County San Juan				
THIS IS A REPORT OF: (Check appropriate block)									
Beginning Drilling Operations Casing Test and Cement Job Cther (Explain):									
Plugging Remedial Work Repair hole in Casing.									÷
Moved in service unit, killed well w/water, ran Welex Corresion Log and holes indicated at 720° and 1128°. Squeezed each zone w/75 sacks Class A Cement. WOC 24 hrs. Found top cement @ 658° & cleaned out to 5038°. Pressured casing to 1000 psi for 30 min. Held o.k. Re-run 171 jts 2-3/8" tubing landed 5250°. Put well on sales line, 9-24-62.									
Witnessed by Position				MEDIAL	Company				
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY  ORIGINAL WELL DATA									
D F Elev. TD 5510' PBTD 54				5400*	ю•		g Interval	Completion Date	
Tubing Diameter Tubing Depth 5241			Oil String Diam		ng Diame	eter Oil Strin		5219	
Perforated In	terval(s)								
Open Hole Interval					Producing Formation(s)  Mesaverde				
			RESULT:	OF WOR	OVER				
Test	Date of Test	Oil Production BPD		oduction FPD		Production PD	GOR Cubic feet/F		s Well Potential MCFPD
Before Workover	9-23-61	<del></del>					****		776
After Workover	Well to be	scheduled for	deliver	ability	test.				
OIL CONSERVATION COMMISSION					I hereby certify that the information given above is true and complete to the best of my knowledge.				
Approved by Original Signed Emery C. Arnold					Name & Suyun E. W. Guynn				
Title Supervisor Dist. # 3					Position District Engineer				
SEP 2 7 1962					Company Delhi-Tayler Oil Corporation				

CONSTRUCTOR OF CONSTR