

DELHI OIL CORPORATION  
1315 PACIFIC AVENUE  
DALLAS 1, TEXAS

Farmington District Office  
P. O. Box 1175  
Farmington, New Mexico



August 14, 1951

Ref: Santa Fe 078201

Mr. P. T. McGrath  
U.S.G.S.  
Box 205  
Farmington, New Mexico

Dear Sir:

Attached hereto form 9-331a covering Subsequent Report of Shooting or Acidizing and Subsequent Report of Redrilling or Repair for Florence Well No. 1-4 located in SW 1/4 of Section 10, T-30-N, R-9-W, San Juan County, New Mexico.

Yours very truly,

A handwritten signature in cursive script, appearing to read "J. B. Howell".

J. B. Howell  
Superintendent

GAF/f  
attach.

cc: Mr. Al Greer ✓



DELHI OIL CORPORATION  
1212 PACIFIC AVENUE  
DALLAS 1, TEXAS

Washington District Office  
P. O. Box 1115  
Washington, New Mexico

August 14, 1951

Mr. J. Edgar Hoover

~~Mr. J. Edgar Hoover~~  
~~P. O. Box 1115~~  
~~Washington, New Mexico~~

Dear Sir:

Attached hereto from 9-2511 covering subsequent report of shooting or holding and subsequent report of retreating or repair for clearance will No. 1-A located in SW 1/4 of Section 10, T-30-N, R-9-W, San Juan County, New Mexico.

Very truly,

*[Handwritten signature]*

J. M. Howell  
Superintendent

CMV  
attach.

cc: Mr. J. Edgar Hoover

STATE OF NEW MEXICO  
OIL CONSERVATION  
COMMISSION

DISTRICT NO. 3  
Phone 99 P. O. Box 697  
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Santa Fe

Land Office 070202

Lease No.

Unit

RECEIVED

AUG 16 1951

CON. COM.

DIST 3

|                                                |                                            |                                     |
|------------------------------------------------|--------------------------------------------|-------------------------------------|
| NOTICE OF INTENTION TO DRILL                   | SUBSEQUENT REPORT OF WATER SHUT-OFF        | <input checked="" type="checkbox"/> |
| NOTICE OF INTENTION TO CHANGE PLANS            | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | <input type="checkbox"/>            |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF     | SUBSEQUENT REPORT OF ALTERING CASING       | <input checked="" type="checkbox"/> |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF REDRILLING OR REPAIR  | <input type="checkbox"/>            |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE        | SUBSEQUENT REPORT OF ABANDONMENT           | <input type="checkbox"/>            |
| NOTICE OF INTENTION TO PULL OR ALTER CASING    | SUPPLEMENTARY WELL HISTORY                 | <input type="checkbox"/>            |
| NOTICE OF INTENTION TO ABANDON WELL            |                                            | <input type="checkbox"/>            |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 14,

51

Flores

19

Well No. 1-4 is located 1700 ft. from N line and 990 ft. from E line of sec. 10  
SW 1/4 Sec. 10 T-10-S R-9-W

(1/4 Sec. and Sec. No.)  
Blanco-La Plata

(Town)  
San Juan

(Range)

(Meridian)  
New Mexico

(Field)

(County or Subdivision)

(State or Territory)

6277

DF

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was deepened to new T.D. of 5510' from original T.D. of 5346' using combination rotary-cable rig using gas to drill, well was shot with 660 lbs of SNG 5290' to 5510'. Ran 2" tubing landed at 5339', tree is set and well is now shut in for test.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Dalhi Oil Corporation

Company

P. O. Box 1175

Address

Farmington, New Mexico

By

Superintendent

Title

Land Office \_\_\_\_\_  
Lease No. \_\_\_\_\_  
Unit \_\_\_\_\_

(SUBMIT IN TRIPLICATE)  
**UNITED STATES**  
**DEPARTMENT OF THE INTERIOR**  
**GEOLOGICAL SURVEY**

STATE OF NEW MEXICO  
**OIL CONSERVATION**  
**COMMISSION**  
DISTRICT NO. 3  
P. O. Box 697  
ALBUQUERQUE, NEW MEXICO



**SUNDRY NOTICES AND REPORTS ON WELLS**

|                                                |  |                                            |
|------------------------------------------------|--|--------------------------------------------|
| NOTICE OF INTENTION TO ABANDON WELL            |  | SUPPLEMENTARY WELL HISTORY                 |
| NOTICE OF INTENTION TO PULL OR ALTER CASING    |  | SUBSEQUENT REPORT OF ABANDONMENT           |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE        |  | SUBSEQUENT REPORT OF REDRILLING OR REPAIR  |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL |  | SUBSEQUENT REPORT OF ALTERING CASING       |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF     |  | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO CHANGE PLANS            |  | SUBSEQUENT REPORT OF WATER SHUT-OFF        |
| NOTICE OF INTENTION TO DRILL                   |  |                                            |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. \_\_\_\_\_ is located \_\_\_\_\_ ft. from \_\_\_\_\_ line and \_\_\_\_\_ ft. from \_\_\_\_\_ line of sec. \_\_\_\_\_  
(Range) (Twp.) (Meridian) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casing; indicate mudding jobs, cementing points, and all other important proposed work)

\_\_\_\_\_

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

\_\_\_\_\_  
Geological Survey

Company \_\_\_\_\_

Address \_\_\_\_\_

By \_\_\_\_\_

Title \_\_\_\_\_