CEMENTING SERVICE TICKET

Blackmon CEMENTING SERVICE

P. O. Box 1217

FARMINGTON, NEW MEXICO

DATE 12/28/61

Nº 189

WELL OWNER John J. Moye

FARM WELL No Jones #1

COUNTY STATE San Juan NM

CHARGE TO Frank Yockey

STREET 821 Crestview Dr

CITY & STATE Farmington NM

TYPE OF JOB Plug & Abandon

TAKEN FT. SIZE 5 1/2" WT.

DEPTH

CONTRACTOR Frank Yockey

ADDRESS 821 Crestview Dr.

CITY & STATE Farmington, NM

CEMENT LEFT IN CASING

MEASURED WITH LINE

CIRC MIN. MAX.

PRESSURES: 150

FLOAT EQUIP.

CENT. & SCRATCHERS

FLOAT COLLAR

SHOE

PLUG BUMPED?

PLUGS:

TOP:

BOTTOM

CEMENT

AMOUNT 100

WT. 15.5

KIND AND AMOUNT OF MIX

TRUCK CALLED OUT 11AM

ON JOB 12:30

JOB BEGAN 2PM

JOB COMPLETED 3PM

[illegible]	15	00
MILEAGE		
WAITING TIME		
ADDITIONAL CHARGE		
SUB TOTAL		
SALES TAX	3	04
TOTAL	155	04

CEMENTER: Woody Blackmon

DRIVER: John Smock

TRUCK:

Blackmon Cementing Service shall not be liable for damage to property of well owner and/or lessee unless caused by its willful or negligence. This provision applying but not limited to subsurface damage or surface damage arising from subsurface damage. Well owner and/or customer shall be responsible for reservoir loss or damage or property damage arising from a well blowout, unless such loss and damage is caused by the willful negligence of Blackmon Cementing Service. If equipment or instruments of Blackmon Cementing Service are lost or damaged at the well site, well owner and/or customer shall either recover the [illegible] or pay the replacement [illegible] Blackmon Cementing Service.

Well Owner, Operator or Contractor

Date_____ Time_____

REMARKS: Spot 40 sks Cement from T.D. to 1700' displace with mud. Spot 60 sks Cement from 414 To Top.

JAN 15 1962
OIL CON. COM.
DIST. 3