

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☒ - Injection
well well

2. NAME OF OPERATOR ARCO Oil & Gas Co., Div. of
Atlantic Richfield Company

3. ADDRESS OF OPERATOR 707-17th Street,
P.O. Box 5540, Denver, CO 80217

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17
below.) Unit "P"
AT SURFACE: 990' FSL & 330' FEL, Sec. 9
AT TOP PROD. INTERVAL: Appx. same
AT TOTAL DEPTH: Appx. same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☒

5. LEASE

NM04444-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Horseshoe Gallup Unit

8. FARM OR LEASE NAME

Horseshoe Gallup Unit

9. WELL NO.

274

10. FIELD OR WILDCAT NAME

Horseshoe Gallup Unit

11. SEC., T., R., M., OR BLK. AND SURVEY OR
AREA

Sec. 9-30N-16W

12. COUNTY OR PARISH 13. STATE

San Juan

New Mexico

14. API NO.

None Assigned

15. ELEVATIONS (SHOW OF. KDB. AND WD)
5397' GR

(NOTE: Report results of multiple completion or zone
change on Form 9-330.)

JAN 05 1984

OIL CON. DIV.

DIST. 9

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates,
including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and
measured and true vertical depths for all markers and zones pertinent to this work.)*

ARCO has plugged and abandoned the subject well in accordance with the Sundry
Notice dated December 30, 1982, and approved by the BLM-MMS on January 11, 1983.
Injection interval 1364' - 1442' OA, Gallup fm. Spotted cement plugs
as per the attached plugging operations report.

Completed P & A, 9-1-83.

Final restoration will be commenced as soon as weather permits. An additional
subsequent report will be filed when restoration has been completed.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Stephen Rose TITLE Dist. Prod. Supt. DATE November 30, 1983
S. C. Rose

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL IF ANY:

NMOCC

HSG #274 .. Horseshoe Gallup Field

P & A OPERATIONS:

MI RU 8/31/83, Rel'd pkr & POH. RIH w/OE tbq & sptd 20 sx cmt across perfs. PU 15 jts tbq & SDON.

FINAL REPORT - WELL P & A 9/1/83

Perf'd 4 holes @ 1216', sptd 30 sx cmt & sqz'd 20 sx thru perfs. Perf'd 2 holes @ 138' & pmpd 30 sx cmt leaving csg full of cmt. Cut wellhd off & instl'd DH marker.