

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☒ - Injection
well ☐ well ☐

2. NAME OF OPERATOR ARCO Oil & Gas Co., Div. of
Atlantic Richfield Company

3. ADDRESS OF OPERATOR 707-17th Street,
P.O. Box 5540, Denver, CO 80217

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17
below.) Unit "J"
AT SURFACE: 1450' FSL & 1980' FEL, Sec. 9
AT TOP PROD. INTERVAL: Appx. same
AT TOTAL DEPTH: Appx. same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☒

5. LEASE
S.F. 081226

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
Horseshoe Gallup Unit

8. FARM OR LEASE NAME
Horseshoe Gallup Unit

9. WELL NO.
275

10. FIELD OR WILDCAT NAME
Horseshoe Gallup Unit

11. SEC., T., R., M., OR BLK. AND SURVEY OR
AREA
Sec. 9-30N-16W

12. COUNTY OR PARISH 13. STATE
San Juan New Mexico

14. API NO.
None Assigned

15. ELEVATIONS (SHOW DF, KDB, AND WD)
5285' GR

(NOTE: Report results of multiple completion or
change on Form 9-330)

RECEIVED
OIL CON. DIV.
DEC 3 1983

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

ARCO has plugged and abandoned the subject well in accordance with the Sundry Notice dated December 30, 1982, and approved by the BLM-MMS on January 11, 1983. Injection interval 1114' - 1195', Gallup fm. Spotted cement plugs as per the attached plugging operations report.

Completed P & A, 9-8-83.

Final restoration will be commenced as soon as weather permits. An additional subsequent report will be filed when restoration has been completed.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Stephen Rose TITLE Dist. Prod. Supt. DATE November 30, 1983
S. C. Rose

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

NO-000

HSG #275

Horseshoe Gallup Field

P & A OPERATIONS:

MI RU 9/1/83; Rel'd pkr & POH. RIH w/OE tbg & SDON.

SD f/rig repairs. SD over weekend.

SD f/rig repairs.

Sptd 20 sx cmt across Gallup. PU 15 jts & SDON.

FINAL REPORT - WELL P & A 9/8/83;

Perf'd 4 holes @ 964', pmpd 30 sx cmt & sqz'd 20 sx thru perfs. PU tbg,
perf'd 2 holes @ 150' & sptd 30 sx cmt leaving csg full of cmt. Cut wellhd
off & instl'd DH marker.