



**NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emnrds.state.nm.us/ocd/DistrictIII/3ddistrict.htm>

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 6/19/99 Operator Conoco API #30-0  
Property Name Faye Burdette Well No. 1 Location: Unit 6 Section 9 Township 30 Range 11  
Pressure (Shut-In or Producing) Tubing 283 Intermediate — Casing 399 Bradenhead 112

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes			Steady Flow <u>50 sec</u>	
10 minutes			Surges	
15 minutes			Down to Nothing	
20 minutes			Nothing	
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR X FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

REMARKS:

Bradenhead blew hard for 50 sec then H<sub>2</sub>O slugs. Casing pressure dropped to 353 after 9 min - bradenhead still blowing steady - probably casing leak.

By \_\_\_\_\_ Witness Bruce Marti

(Position)