Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Budget Bureau No. 1004-0135 Expires: March 31, 1993	/	FORM	APPROVED
Expires: March 31, 1993	/B	udget Bur	eau No. 1004-0135
	_	Expires:	March 31, 1993

(Note: Report results of multiple completion on Well

Completion or Recompletion Report and Log form.)

DISTRICT MANAGER

<u>ivivilvivi077</u>

Do not use this form for proposals to di Use "APPLICATION FO	6. If Indian, Allottee or Tribe Name	
SUBMIT	7. If Unit or CA, Agreement Designation	
I. Type of Well Oil Well Well Well Other		8910066740
		8. Well Name and No.
2. Name of Operator		NE Hogback Unit #29
Condor Vil Corporation		9. API Well No.
3. Address and Telephone No.	30045097330081	
3860 Carlock Drive, Bould	10. Field and Pool, or Exploratory Area	
3860 Carlock Prive, Bould 4 Location of Well (Footage, Sec., T., R., M., or Survey D	Horseshoe	
2090' FNL & 2190' FWL, Se	11. County or Parish, State	
200 2112 0 2270 2112, 20	San Juan County	
		New Mexico
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE. REPOR	
TYPE OF SUBMISSION	TYPE OF ACTION	
X Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	
Final Adamonment Notice	X other shut-in injection	Conversion to Injection
	LAJ Otner SILUC-III II, [a CLOII	_ L Dispose Water

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated after the starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work. 1*

well

According to the records received by Condor from BHP Petroleum, this well has been shut-in since June, 1972. Prior to that, it was an injection well with a model P packer set @ 1877'. Since that packer is between the Upper Gallup perfs from 1890' to 1916', it would not be able to conduct a casing integrity test without considerable expense for pulling and testing. Last year, the Upper Gallup perforations in the angles were swab tested and the fluid level was found to be 900' from the surface. The calculated top of cement behind the $4\frac{1}{2}$ " csg. is 823' and the base of the Mesaverde is 460', so there can be no water flow into sands in the Mesaverde. In addition, the Mesaverde in the area of the unit does not contain potable water so there is no potential for pollution. Therefore, Condor requests approval to keep this well shut-in until it has completed infill development and resumed full scale waterflood operations at which time this well will be of use.

	THIS AFPROVAL EXPINED	CO 9 1994	
14. I hereby certify that the foregoing is true and correct Signed	Contract Opera Title Condor Oil Cor	itor for position	Date Dec. 22, 1993
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title		APPROVED
Title 18 U.S.C. Section 1001, makes it a crime for any person representations as to any matter within its jurisdiction.	on knowingly and willfully to make to any department o	or agency of the United State	es any false, fictitious or fraudulent statemer