5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR

DEPARTMENT OF THE INTERIOR	S.F. 081226-C
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	USA
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
Do not use this form for proposals to drill or to deepen or plug pack to a different eservoir. Use Form 9-331-C for such proposals.)	Horseshoe Gallup Unit 8. FARM OR LEASE NAME
eservoir. Use Form 3-331-C for secti proposition	
1. oil gas	Horseshoe Gallup Unit
well — well — other X - Injection	9. WELL NO. 269
2. NAME OF OPERATOR ARCO Oil & Gas Co., Div. of	10. FIELD OR WILDCAT NAME
Atlantic Richfield Company	Horseshoe Gallup Unit
3. ADDRESS OF OPERATOR 707-17th Street,	11. SEC., T., R., M., OR BLK, AND SURVEY OR
P.O. Box 5540, Denver, CO 80217 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.) Unit "H"	Sec. 9-30X-16W
AT SURFACE: 1746' FNL & 1122' FEL, Sec. 9	12. COUNTY OR PARISH: 13. STATE
AT TOP PROD. INTERVAL: Appx. same	San Juan New Mexico
AT TOTAL DEPTH: Appx. same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	None Assigned
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	5462' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT	
REPAIR WELL	(NOTE: Report results of multiple demalation of zone
PULL OR ALTER CASING	change on Form 3-330.1
MULTIPLE COMPLETE	200 1984 U
CHANGE ZONES	6 2 € 40 €
(other) F4704 50 for	
	2:31. 3
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is different and true vertical depths for all markers and zones pertinent.)	e all pertinent details, and give pertinent dates, irectionally drilled, give subsurface locations and it to this work.)*
ARCO has plugged and abandoned the subject well	
Notice dated December 30, 1982, and approved by	·
	Gallup fm. Spotted cement plugs
as per the attached plugging operations report	•
Completed P & A, 8-31-83.	
Final restoration will be commenced as soon as	weather normits' in additional
subsequent report will be filed when restoration	
	on has been completed.
Cubaudaaa Salahi Value Manu and Tuna	Sat @ 54
Subsurface Safety Valve: Manu. and Type	Set @ Pt
18. I hereby certify that the foregoing is true and correct	
Stephen Rose Time Dist. Prod. Su	pt. DATE November 30, 1983
SIGNED S. C. Rose TITLE DISC.FIOU. 34	- Unit
(This space for Federal or State of	fice use)
APPROVED BY TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	

HSG #269 Horseshoe Gallup Field

P & A OPERATIONS:

MI RU 3/30/83 Pmpd 20 sx cmt across perfs & SDON.

FINAL REPORT - WELL P & A 8/31/83. Perf'd 4 holes @ 1095', pmpd 30 sx cmt & sqz'd 20 sx thru perfs. PU tbg, perf'd 2 holes @ 134' & pmpd 30 sx cmt leaving csg full of cmt. Cut wellhd off & instl'd DH marker.