

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☒ - Injection  
well ☐ well ☐
2. NAME OF OPERATOR ARCO Oil & Gas Co., Div. of  
Atlantic Richfield Company
3. ADDRESS OF OPERATOR 707-17th Street,  
P.O. Box 5540, Denver, CO 80217
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17  
below.) Unit "D"  
AT SURFACE: 560' FNL & 660' FWL, Sec. 9  
AT TOP PROD. INTERVAL: Appx. same  
AT TOTAL DEPTH: Appx. same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,  
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐ ☐

FRACTURE TREAT ☐ ☐

SHOOT OR ACIDIZE ☐ ☐

REPAIR WELL ☐ ☐

PULL OR ALTER CASING ☐ ☐

MULTIPLE COMPLETE ☐ ☐

CHANGE ZONES ☐ ☐

ABANDON\* ☐ ☒

(other) ☐ ☐

5. LEASE  
S-F-081226-A
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
USA
7. UNIT AGREEMENT NAME  
Horseshoe Gallup Unit
8. FARM OR LEASE NAME  
Horseshoe Gallup Unit
9. WELL NO.  
261
10. FIELD OR WILDCAT NAME  
Horseshoe Gallup Unit
11. SEC., T., R., M., OR BLK. AND SURVEY OR  
AREA  
Sec. 9-30N-16W
12. COUNTY OR PARISH: 13. STATE  
San Juan New Mexico
14. API NO.  
None Assigned
15. ELEVATIONS (SHOW DF, KDS, AND WD)  
5299' GR

RECEIVED  
(NOTE: Report results of multiple completion or change on Form 9-331-C)  
JAN 6 1984  
OIL CON. DIV.  
DIST. 3  
BUREAU OF LAND MANAGEMENT  
FEDERAL GEOLOGICAL SURVEY

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*
- ARCO has plugged and abandoned the subject well in accordance with the Sundry Notice dated December 30, 1982, and approved by the BLM-MMS on January 11, 1983. Injection interval 1066' - 1107', Gallup fm. Spotted cement plugs as per the attached plugging operations report.

Completed P & A, 9-19-83.

Final restoration will be commenced as soon as weather permits. An additional subsequent report will be filed when restoration has been completed.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Stephen Rose TITLE Dist.Prod. Supt. DATE November 30, 1983  
S. C. Rose

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

MOCC