Fcrm 3160-5 (November 1983) (Formerly 9-331)

## UNITED STATES DEPARTMENT OF THE INTERIOR

SUBMIT				
(Other )		uctions	οn	re-
verse side	• )			

Form approved. Budget Bureau Nov 1004-1, 1 Expires August 31, 1985 5 LEASE DESIGNATION AND SERIAL NO.

		-
SF-0794939	<i>.</i> •;	07943
F INDIAN ALLOTTER OR		

<u> Korseshoe Gallup U</u>nit

BUREAU OF LAND MANAGEMENT	1	SF-0794939 1 6/942
SUNDRY NOTICES AND REPORTS ON WELLS	6	F INDIAN ALLOTTER OR TRIBE NAME

	. /
COUNTR	∠ Navajo
OL! VLU	7. JINIT AGREEMENT !

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir

Use "APPLICATION FOR PERMIT" for such proposals.

OIL X GAS WELL OTHER NAME OF OPERATOR NOV

ARCO Oil and Gas Company

3. ADDRESS OF OPERATOR

TEST WATER SHUT-OFF

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

**BUREAU OF LAND MANAGEMENT** FARMINGTON RESOURCE AREA

P. O. Box 1610, Midland, Texas 79702 FARMINGTON RESOLUTION OF WELL (Report location clearly and in accordance with any State requirements.)

At surface

Hnit "M" Unit " M

330' FSL & 4510' FEL, Sec. 4 15 ELEVATIONS (Show whether DF, RT, GR, etc.)

5303' KB No API NO. Assigned

<u> Horseshoe Gallup Unit</u> 252 10. FIELD AND POOL, OR WILDCAT

Horseshoe Gallup
11. SBC., T., R., M., OR BLE. AND
SURVEY OR ARMA

Sec 4-30N-16W 12. COUNTY OR PARISH 13. STATE <u>San Juan</u> N M

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

PULL OR ALTER CASING

ARANDONS CHANGE PLANS SUBSEQUENT REPORT OF:

WATER SHUT-OFF

SHOOTING OR ACIDIZING

REPAIRING WELL

ABANDON MENT®

NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form. 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

This well was plugged 11/8/84 - 11/12/84 as follows:

Plug	<u>Interval</u>	<u>Cement</u>	
1	745 - 1133	45 sx	Spotted plug to cover Gallup perfs 1059 - 72, 1094 - 98, 1101 - 17 and 1125 -33.
2	53 - 153	55 sx	Squeezed 2 perforations at $153$ 'w/30 sx to isolate the estimated TOC at 320'. Left a 100' cement plug inside the $5-1/2$ " casing. Pumped 25 sx down the $8-5/8$ " X $5-1/2$ " annulus.
3	0 - 30	5 sx	Spotted a 5 sk plug at surface.

Welded a steel plate over the top & installed a dry hole marker.

18. I hereby certify that the foregoing is true a signed Ken W Lound		ADDIOVED  DATE 11-7-86	
(This space for Federal or State office use)  APPROVED BY	TITLE	NOV 1	-
CONDITIONS OF APPROVAL, IF ANY:	Approved as the single or since real tages. Liability under the for eaching Last, surface resident to be a content.	FARMINGTON TO	
	*See Instructions on Reverse Side	TALL THE REPORT OF THE PARTY OF	