

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐  
well well other

2. NAME OF OPERATOR  
R & G DRILLING COMPANY

3. ADDRESS OF OPERATOR c/o Walsh Engr. & Prod.  
P. O. Drawer 419 Farmington, N.M. 87409

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 790' FSL, 790' FWL  
AT TOP PROD. INTERVAL: Same  
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) See Below

SUBSEQUENT REPORT OF

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

RECEIVED  
MAR 17 1983

U.S. GEOLOGICAL SURVEY  
FARMINGTON, N.M.

5. LEASE  
NM 09867-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Lunt

9. WELL NO.  
67

10. FIELD OR WILDCAT NAME  
Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 6-T30N-R13W  
N.M.P.M.

12. COUNTY OR PARISH  
San Juan

13. STATE  
N.M.

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
5658

NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Gas production stopped due to fluid eating into well bore. Swab test of fluid indicates old drilling mud.
2. It is proposed to pull tubing and run tubing with packer to determine amount of damage to formation.

Permission is requested to install packer to determine producing capacity of Dakota Formation. Within 30 days information will be submitted as to repair to prevent fluid entry or plug as abandon well.

Verbal permission received March 16, 1983.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

FOR: R & G DRILLING COMPANY

18. I hereby certify that the foregoing is true and correct

SIGNED EWELL N. WALSH TITLE Walsh Engr. & Prod. Corporation DATE 3/17/83  
Ewell N. Walsh, President

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_ DATE \_\_\_\_\_

*James E. Smith*  
JAMES E. SMITH

\*See Instructions on Reverse Side

NMOCC