Form 3160-5		FORM ADDROVED
(June 1990)	<i>/</i> ·	FORM APPROVED
		Budget Bureau No. 1004-0135 Expires: March 31, 1993
	NITED STATES	5. Lease Designation and Serial No.
DEPARTMENT OF THE INTERIOR		
		1: 117   SF-081226 6. If Indian, Allottee or Tribe Name
	ES AND REPORTS ON WELLS	. 13 8
Use "APPLICATION	o drill or to deepen or reentry to a different reservoir,  N FOR PERMIT" for such proposals	7. If Unit or CA. Agreement Designation
	TRIPLICATE	Horseshoe Gallup Unit
	Well X Other WIW	8. Well Name and No. HGU #253
2. Name of Operator		9. API Well No.
Central Resources, Inc. c/o Playa Minerals & Energy, Inc.		30-045-09832
3. Address and Telephone No.		10. Field and Pool, or Exploratory Area
650 N. Sam Houston Pkwy E. Suite 500 Houston, Tx 77060		Horseshoe Gallup Unit
4. Location of Well (Footage, Sec., T., R., M.,		11. County or Parish, State
660' FSL, 3300' FEL, Sec. 4, T30N	N, R16W	San Juan County NM
2. CHECK APPROPRIATE BOX(s) TO	INDICATE NATURE OF NOTICE, REPORT, OR (	OTHER DATA
TYPE OF SUBMISSION	TYPE OF AC	ITION
	X Abandonment	Change of Plans
Notice of Intent	Recompletion	New Construction
X Subsequent Report Final Abandonment Notice	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
	Altering Casing	Conversion to Injection
	Other	Dispose Water
		(Note: Report results of multiple completion on Well
2 Describe Proposed on Completed Com	early state all pertinent dates, including estimated date of star	Completion or Recompletion Report and Log form.)
	, , , , , , , , , , , , , , , , , , , ,	ang any proposed work. If well is
directionally drilled, give subsurface locations and See attached report.	nd measured and true vertical depths for all markers and zone	rs pertinent to this work.)*
	nd measured and true vertical depths for all markers and zone	es pertinent to this work.)*
See attached report.	nd measured and true vertical depths for all markers and zone	es pertinent to this work.)*
See attached report.  14. I hereby certify that the foregoing is true a Signed	nd correct  Title Regulatory Compliance	DEC 2 / 1393
See attached report.  14. I hereby certify that the foregoing is true a Signed  Mark L. Ehrman  (This space for Federal or State office use Approved by	nd correct  Title Regulatory Compliance	DEC 2 / 1993  DESTO DUY
See attached report.  14. I hereby certify that the foregoing is true a Signed  Mark L. Ehrman  (This space for Federal or State office use	nd correct  Title Regulatory Compliance	Date 12/10/99

\*See Instruction on Reverse Side

DEMAND FOR RECORD

DEC -2 1 1999

fictitious or fraudulent statements or representations as to any manner within its jurisdiction.



777 ED 16 77 1:49

Key Energy Services, Inc.

Four Corners Division P.O. Box 900 5651 US Highway 64 Farmington, NM 87499

Phone: 505-327-4935 Fax: 505-327-4962

## P&A OPERATION CEMENT SERVICE REPORT

WELL NAME: HORSESHOE GALLUP UNIT #253

TOTAL PLUGS SET: 1

DATE STARTED: 11-11-98

**TOTAL SACKS USED: 176 sx.** 

DATE COMPLETED: 11-14-98

BLM WITNESS: J. SANCHEZ OPERATOR WITNESS: N/A

MOL AND RU RIG. BLEED DOWN WELL AND ND WELLHEAD. TUBING SLIPS STUCK IN BOWL. REMOVE SLIPS. WORK TUBING AND RELEASE PACKER. POH WITH 30 JOINTS OF 2 3/8" TUBING. PACKER STUCK AT 142'. ATTEMPT TO PUSH PACKER DOWN BUT WAS STUCK AT 198'. RU PUMP ON CASING AND ESTABLISHED CIRCULATION TO SURFACE WITH WATER OUT THE BRADON HEAD. 5 ½" CASING IS PARTED. BLM APROVED CHANGE IN PROCEDURE.

PLUG #1 (0' - 142'),

RIH WITH 2 3/8" TUBING CUTTER AND TAGGED AT 112'. CUT OFF TUBING AT 110' AND POH. MIXED 48 SX CL. B CEMENT TO CIRCULATE GOOD CEMENT TO SURFAXE. RD FLOOR AND CUT OFF WELLHEAD. TOPPED OFF CASINGS WITH 128 SX CL. B CEMENT. RD RIG AND MOL.

NATHAN E. CRAWFORD.
P&A SUPERVISOR