

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ well ☐ other ☒ - Injection
2. NAME OF OPERATOR ARCO Oil & Gas Co., Div. of  
Atlantic Richfield Company
3. ADDRESS OF OPERATOR 707-17th Street,  
P.O. Box 5540, Denver, CO 80217
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17  
below.) Unit "P"  
AT SURFACE: 695' FSL & 835' FEL, Sec. 3  
AT TOP PROD. INTERVAL: Appx. same  
AT TOTAL DEPTH: Appx. same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,  
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

SUBSEQUENT REPORT OF:

- ☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☒

5. LEASE

S.F. 081226

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Horseshoe Gallup Unit

8. FARM OR LEASE NAME

Horseshoe Gallup Unit

9. WELL NO.

259

10. FIELD OR WILDCAT NAME

Horseshoe Gallup Unit

11. SEC., T., R., M., OR BLK. AND SURVEY OR  
AREA

Sec. 3-30N-16W

12. COUNTY OR PARISH: 13. STATE

San Juan New Mexico

14. API NO.

None Assigned

15. ELEVATIONS (SHOW DF, KDB, AND WD)

5556' GR

RECEIVED

(NOTE: Report results of multiple completion change on Form 9-330.)

DEPT. OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

JAN 06 1984

GIL CON. DIV.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

ARCO has plugged and abandoned the subject well in accordance with the Sundry Notice dated December 30, 1982, and approved by the BLM-MMS on January 11, 1983. Injection interval 1464' - 1600' OA, Gallup fm. Spotted cement plugs as per the attached plugging operations report.

Completed P & A, 8-25-83.

Final restoration will be commenced as soon as weather permits. An additional subsequent report will be filed when restoration has been completed.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Stephen Rose TITLE Dist.Prod. Supt. DATE November 30, 1983  
S. C. Rose

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

NMOCC

HSG #259, Horseshoe Gallup Field

P & A OPERATIONS:

MI & RU 8/25/83. 'Rel'd pkr. POH w/ 1-1/2 jts & pkr stuck. Backoff tbg @ safety jt. Spt 20 sx plug & POH w/20 jts tbg. SDON.

FINAL REPORT - WELL P & A, 8/25/83

Perf'd 4 holes @ 1314'. Spt 38 sx cmt. Sqz 20 sx thru perfs. Perf'd 2 holes @ 150'. Load csg w/30 sx cmt. Cut off wellhd. Instl'd DH marker. RD & MO 8/25/83.