

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Land Office Santa Fe
Lease No. NM-09867-A
~~XXXX~~ Lunt

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 5, 1961, 19

Well No. 64 is located 790 ft. from N line and 1090 ft. from E line of sec. 5


SW/4 Sec. 5 30 N 13 W NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5625 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plan to drill 12 3/4" surface hole - set 250' x 36# casing with 200 sacks neat cement. 7 7/8" hole with mud to TD of 6350', thru Dakota formation. 4 1/2" x 11.60# casing to TD with 200 sacks cement. Perforate Dakota and sand-water frac.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company R & G Drilling Company, Inc.
12 West 72nd Street
Address New York 23, N. Y.

By William C. Russell
Title President

NEW MEXICO OIL CONSERVATION COMMISSION

Well Location and Acreage Dedication Plat

Section A.

Date 12-5-61

Operator R AND G DRILLING COMPANY Lease Lunt
 Well No. 64 Unit Letter M Section 5 Township 30 NORTH Range 13 WEST, NMPM
 Located 790 Feet From the SOUTH Line, 1090 Feet From the WEST Line
 County SAN JUAN G. L. Elevation 5614.0 Dedicated Acreage 320 W 320.72 Acres
 Name of Producing Formation Dakota Pool Wildcat

1. Is the Operator the only owner in the dedicated acreage outlined on the plat below?
 Yes X No _____
2. If the answer to question one is "no", have the interests of all the owners been consolidated by communitization agreement or otherwise? Yes _____ No _____. If answer is "yes", Type of Consolidation _____
3. If the answer to question two is "no", list all the owners and their respective interests below:

Owner

Land Description

RECEIVED

DEC 8 1961

OIL CON. COM.
DIST. 3

RECEIVED

DEC 7 1961

U. S. GEOLOGICAL SURVEY

Section B.

Note: All distances must be from outer boundaries of section.

This is to certify that the information
 in Section A above is true and complete
 to the best of my knowledge and belief.

R & G Drilling Company, Inc.

(Operator)

William C. Russell


(Representative)

Box 327

(Address)

Farmington, N. M.

Ref: GLO plat dated 12 May 1955



0 330 660 990 1320 1650 1980 2310 2640 2970 3300 3630 3960 4290 4620 4950 5280 5610 5940 6270 6600 6930 7260 7590 7920 8250 8580 8910 9240 9570 9900 0

Scale 4 inches equal 1 mile

This is to certify that the above plat was prepared from field notes of actual surveys
 made by me or under my supervision and that the same are true and correct to the best
 of my knowledge and belief.

(Seal)

Date Surveyed 5 December 1961

Farmington, New Mexico

Registered Professional Engineer and/or Land Surveyor
James P. Leese M. Mex. Reg. No. 1463