

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 43-R388.4
Approval expires 12-31-60.

Land Office Santa Fe
Lease No. 081226-B
Unit Bolack

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	☒
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 21st, 1959

Well No. 11 is located 860 ft. from N line and 1780 ft. from E line of sec. 4
SW/4 SE/4 Sec. 4 10N 16W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Horseshoe Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 5669 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

12-17-58 TD 1589' RKB. Set 51 joints 1584' of 5-1/2" OD 14# J-55 casing at 1588' with 75 sacks cement, 2% gel, 1/4# floccle per sack, 500# mica.

12-17-59 Pressured up on casing to 1000#. No pressure decrease in one hour.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company TOM BOLACK
 Address 1010 North Dustin
Farmington, New Mexico

By Tom Bolack
 Title _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

11-22-20 10:00 AM
11-22-20 10:00 AM

○		

SUNDRY NOTICES AND REPORTS ON WELLS

SUNDRY NOTICES	
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLUMB	SUBSEQUENT REPORT OF SHOOTING OR FLOODING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALLEVIATING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHUT OR ADJUST	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO TIE IN AFTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

DATE OF REPORT: 10/10/78

91

[illegible]

...the ... of ...

DETAILS OF WORK

DETAILS OF WORK

THE UNIVERSITY OF CHICAGO

[Faint, illegible markings]

1. The first step in the process of identifying a problem is to define the problem. This involves identifying the symptoms of the problem and determining the scope of the problem. Once the problem has been defined, the next step is to identify the causes of the problem. This involves identifying the factors that are contributing to the problem and determining the root cause of the problem. Once the causes of the problem have been identified, the next step is to develop a plan to address the problem. This involves identifying the actions that need to be taken to address the problem and determining the resources that will be needed to implement the plan. Once a plan has been developed, the next step is to implement the plan. This involves taking the actions that have been identified in the plan and monitoring the progress of the plan. Finally, the last step in the process is to evaluate the results of the plan. This involves determining whether the plan has been successful in addressing the problem and identifying any lessons learned from the process.

[illegible]

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED



LTR



Job separation sheet

		X	
		X	

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **081226-B**
Unit **Bolack**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 21st 19 59

Well No. 11 is located 860 ft. from N line and 1780 ft. from E line of sec. 4
SW/4 SE/4 Sec. 4 30N 16W N.M.P.M.
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Horseshoe Gallup San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5669 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

12-11-58 TD 102' RKB. Set 3 joints 93' of 8-5/8" OD 24# J-55 casing at 102' with 70 sacks cement, circulated to surface.

12-13-58 Pressured up on casing to 500#. No pressure decrease in 30 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.


Company TOM BOLACK

Address 1010 North Dustin
Farmington, New Mexico

By Don Dolack
Title _____

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUBSEQUENT REPORT OF CLOSING OR ACIDIZING
NOTICE OF INTENTION TO STOP OR ALTER	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REPAIR OR	SUBSEQUENT REPORT OF REPAIRING OR REPAIR
NOTICE OF INTENTION TO STOP OR ALTER	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	OTHER REPORTS WELL HISTORY

INDICATE ABOVE BY CHECK IN NATURE OF REPORT (OR OTHER DATA)

Well No. _____ is located _____ ft. from _____ and _____ ft. from _____ line of sec. _____

County _____ State _____

Topography _____

Water _____

Other _____

The elevation of the datum foot above sea level is _____ ft.

DETAILS OF WORK

Describe here in brief the nature of the work done, including the results of the work, and the amount of material used, and the cost of the work.


1. _____

2. _____

3. _____

4. _____

5. _____



Witnessed and attested the _____ day of _____ 19____

Special Agent in Charge

Geologist

This _____