

## OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil &amp; Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER-

Name of Operator

C. &amp; E. Operators, Inc.

Address of Operator Suite 1100, Two Energy Square

4849 Greenville Ave., Dallas, Texas 75206

Location of Well

 UNIT LETTER J 1673 FEET FROM THE South LINE AND 1831 FEET FROM  
 THE East LINE, SECTION 5 TOWNSHIP 30N RANGE 11W NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

Abrams

9. Well No.

1

10. Field and Pool, or Wildcat

15. Elevation (Show whether DF, RT, GR, etc.)

5667' Gr.

12. County

San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

 REFORM REMEDIAL WORK ☐  
 TEMPORARILY ABANDON ☐  
 WELL OR ALTER CASING ☐

 PLUG AND ABANDON ☐  
 CHANGE PLANS ☐
OTHER ☐
 REMEDIAL WORK ☐  
 COMMENCE DRILLING OPNS. ☐  
 CASING TEST AND CEMENT JOBS ☐

 ALTERING CASING ☐  
 PLUG AND ABANDONMENT ☐
OTHER Check for surface gas leaks ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Re: Your letter of 8-10-83. Your recent inspection. - Possible gas leak at surface.

A roustabout crew was sent to location and dug out around well head. Found no leaks except that a 1" ball valve on the bradenhead was weeping water. Bradenhead press. was too small to measure. Made approx. one quart of brackish water and diminished to a water drip. Observed for a period of 1 hour. Replaced valve. Checked gas line from well head to El Paso meter station. No leaks. Intermittent valve had a slight leak. Replaced stem & seat. Dug a small pit to discharge intermittent line into and fenced same. Well unloads a slight condensate & water vapor mist during intermission.

The location area had been sprayed with a sterilizer to prevent weed growth earlier this year. Thus the detection of dead vegetation.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

 SIGNED John M. Heller
TITLE ConsultantDATE Aug. 24, 1983

Original Signed by CHARLES GHOLSON

APPROVED BY \_\_\_\_\_

TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3DATE AUG 24 1983

CONDITIONS OF APPROVAL, IF ANY: