

			X

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **SP**
Lease No. **081226**
Unit **Horseshoe Canyon**

SUNDRY NOTICES AND REPORTS ON WELLS

SUNDRY NOTICES AND REPORTS		DATE	BY
NOTICE OF INTENTION TO DRILL			
NOTICE OF INTENTION TO CHANGE PLANS			
NOTICE OF INTENTION TO TEST WATER SHUT-OFF			
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL			
NOTICE OF INTENTION TO SHOOT OR ACIDIZE			
NOTICE OF INTENTION TO PULL OR ALTER CASING			
NOTICE OF INTENTION TO ABANDON WELL			
SUBSEQUENT REPORT OF WATER SHUT-OFF			
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING			
SUBSEQUENT REPORT OF ALTERING CASING			
SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR			
SUBSEQUENT REPORT OF ABANDONMENT			
SUPPLEMENTARY WELL HISTORY			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 3, 19 58

Well No. 12 is located 1810 ft. from [S] line and 760 ft. from [E] line of sec. 3

Well No. _____

NE SE/4 Sec. 3
(¼ Sec. and Sec. No.)

Horsehoe Gap
(Field)

30N
(Twp.)

16W
(Range)

San Juan
(County or Subdivision)

NMPM
(Meridian)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5707 ft.

DETAILS OF WORK

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud Date 11-29-58. 12-1-58 Total Depth 105'.
Ran 3 joints. 8-5/8", 32.00#, J-55 Casing (93') set at 101' with 75 sacks regular
cement, 2% CaCl₂ circulated to surface.
Held 500#/30 Minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

I understand that this plan of work must be approved by _____
Company El Paso Natural Gas Products Company

Company _____
Address _____ **Post Office Box 1565**
Farmington, New Mexico

ORIGINAL SIGNED BY: JOSEPH E. KREGER

Title Petroleum Engineer