

6-5000
1-Ring
1-Rose
1-Magnolia
1-File

(SUBMIT IN TRIPLICATE)

Budget Bureau No. 42-R359.4.
Approval expires 12-31-60.

Indian Agency Navajo

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 14-20-409-2021

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

RECEIVED
SEP 15 1958
U. S. GEOLOGICAL SURVEY

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 12, 1958

Well No. Navajo
H-1 is located 1980 ft. from N line and 330 ft. from E line of sec. 9
NE 1/4 Sec 9 30 N 17W 100N
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the ~~ground~~ derrick floor above sea level is 9081 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 8-27-58 drilled 9" hole to 60' ran 2 jts 7" OD 20# J-55 casg TE 5891' set @ 59' GL cemented w/20 sz reg. Drilled 6 1/2" hole to 1095' ran 4 1/2" 9.5# J-55 casg TE 1096.50 set @ 1095' GL cemented w/100 sz.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company King Oil Company
Address Val R. Reese & Assoc., Inc.
120 S. Commercial
Farmington, New Mexico

By _____
Title Consulting Engineer