

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo Tribal

Window Rock, Arizona

Allottee _____

Lease No. 149-IND-7653

X		

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 21, 1956

Well No. Navajo is located 310 ft. from S line and 650 ft. from W line of sec. 4 _____


<u>SW 1/4 Sec. 4</u> (1/4 Sec. and Sec. No.)	<u>30 N</u> (Twp.)	<u>17 W</u> (Range)	<u>NMPM</u> (Meridian)
<u>Midland</u> (Field)	<u>San Juan</u> (County or Subdivision)	<u>New Mexico</u> (State or Territory)	

The elevation of the derrick floor above sea level is 5096.7 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Test was snudded March 12, 1956. A 5/8" csg. cemented at 91' 0" with 50 sack bulk cement. Circulated cement to surface. Currently drilling below 300'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Late Oil Company

Address Box 670

San Angelo, Texas

By William H. Anderson

Title Agent