## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

	Budget Bureau No. 42-R1424	
1	5. LEASE 14-20-603-703	
_	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
	7. UNIT AGREEMENT NAME	
t	Horseshoe Gallun Unit	
	8. FARM OR LEASE NAME	
	Horseshoe Gallup Unit	
İ	9. WELL NO.	
132		
_	10. FIELD OR WILDCAT NAME Horseshoe Gallup <del>Unit</del>	
	11. SEC., T., R., M., OR BLK, AND SURVEY OR	
7	sêc. 5-30N-16W	
	12. COUNTY OR PARISH 13. STATE San Juan New Mexico	
_	14. API NO. None Assigned	

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) gas other X - Injection well v.e 2. NAME OF OPERATOR ARCO Oil & Gas Co., Div. of Atlantic Richfield Company 3. ADDRESS OF CPERATOR 707-17th Street, P.O. Box 5540, Denver, CO 80217 4. LOCATION OF WELL REPORT LOCATION CLEARLY. See space 17 below.) Unit "F" AT SURFACE: 1580 AT SURFACE: FNL & 1480 FWL, Sec. 5
AT TOP PROD. INTERVAL: Appx. same AT TOTAL DEPTH: Appx. same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, 15. ELEVATIONS (SHOW DF, KDB, AND WD) 5331' GR REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE DEC ? O NOTE: Report results of mu REPAIR WELL PULL OR ALTER CASING BUREAU OF LAND MAIN GEMENT FARMINGTON RESOURCE AREAS MULTIPLE COMPLETE CHANGE ZONES ABANDON\* (other)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

ARCO has plugged and abandoned the subject well in accordance with the Sundry Notice dated December 30, 1982, and approved by the BLM-MMS on January 13, 1983. Gallup fm. Spotted cement plugs Injection interval 1054' - 1121' OA, as per the attached plugging operations report.

Completed P & A, 9-14-83.

Final restoration will be commenced as soon as weather permits. An additional subsequent report will be filed when restoration has been completed.

Subsurface Safety Valve: Manu, and Type		Set @ Ft.	
18. Thereby certify that the foregoing is to signed Stechen Rase	TITLE Dist.Prod. Supt.	DATE November 30, 1983	
S. C. ROSE (This space for Federal or State office use)			
APPROVED BY	TITLE	_ DATE	

Horseshoe Gallup Field

## P & A OPERATIONS:

MI RU 9/13/83. Rel'd pkr. POH w/tbg. LD pkr. RIH w/tbg OE & spt 30 sx plug. PU 15 jts. SI & SDON.

FINAL REPORT - WELL P & A, 9/14/83. Perf 4 holes @ 904'. Spt 30 sx plug, sqz'd 20 sx thru perfs. POH. Perf 2 holes @ 176'. Pmpd 30 sx plug, w/csg full of cmt. Cut off wellhd. Instl'd DH marker. RD.