


(SUBMIT IN TRIPLICATE)

Indian Agency Navajo

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allettee The Tamm Company
Lease No. 1-119-IND-7653



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 1, 19 61

Well No. A-5 is located 2310 ft. from N line and 330 ft. from W line of sec. 4


<u>SE SE NE 4</u>	<u>30N 17W</u>	<u>100W</u>
(1/4 Sec. and Sec. No.)	(Twp.) (Range)	(Meridian)
<u>Chimney Rock</u>	<u>San Juan</u>	<u>New Mexico</u>
(Field)	(County or Subdivision)	(State or Territory)

The elevation of the derrick floor above sea level is 5116 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 6" hole to 510' encountered cave in hole was unable to drill ahead.
Plan to put a 100' cement plug in bottom and a cement plug from 575' to 475',
cement plug from 150' to surface.
Top of Gilling sand 487' bottom 495' no show of oil in hole



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company King Oil Company
Address 735 Petroleum Club Building
Denver 2, Colorado

By [Signature]
Title President