

(SUBMIT IN TRIPPLICATE)

Indian Agency **Navajo**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Albottas **The Texas Co.**
Lease No. **1-149-IND-7653**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 1, 1961


Navajo
Well No. **A-5** is located **2310** ft. from **N** line and **330** ft. from **E** line of sec. **4**
SE SE NE 4 **30N** **17W** **114PM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Chimney Rock **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5116** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 6" hole to 840' encountered cave in hole was unable to drill ahead.
150' cement plug in bottom and a cement plug from 575' to 475',
cement plug from 150' to surface.
Top of Gallup sand 487' bottom 495' no shows of oil in hole.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **King Oil Company**
Address **735 Petroleum Club Bldg.**
Denver 2, Colorado

By _____
Title **President**