

well file



OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO
1000 RIO BRAZOS RD. - AZTEC

87410

October 1, 1975

I. R. TRUJILLO
CHAIRMAN

LAND COMMISSIONER
PHIL R. LUCERO
MEMBER

STATE GEOLOGIST
A. L. PORTER, JR.
SECRETARY - DIRECTOR

Northwest Production Corp.
202 Petroleum Plaza
Farmington, New Mexico 87501

Larry Van Ryan

Re: Northwest Production Corp.
Blanco 30-12 #1 (FM)
A-4-30N-12W

Gentlemen:

The attached packer-leakage test report for the subject well indicates communication between the producible zones.

You are hereby directed to take immediate action to cause the well to comply with Rule 112-A, Section VI and the order authorizing the multiple completion.

If there are questions, please contact us.

Yours very truly,

A. R. Kendrick
A. R. Kendrick
Supervisor, District #3

ARK:mc

Encl.

cc w/ encl.: Oil Conservation Commission
Santa Fe, New Mexico


NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

Operator Northwest Production Corp.		Well Name and Number Blanco 30-12 #1 (FM)	
Location of Well Unit A Sec. 4 Twp. 30 Rge. 12		Annual - (Give Year) 1975	Initial - (Give Date)
UPPER COMPLETION	Reservoir or Pool FT	☒ GAS ☐ OIL	☒ FLOWING ☐ ARTIFICIAL LIFT
LOWER COMPLETION	Reservoir or Pool MV	☒ GAS ☐ OIL	☒ FLOWING ☐ ARTIFICIAL LIFT
		Production String ☒ CASING ☐ TUBING	
		Production String ☐ CASING ☒ TUBING	

Date	Upper Zone		Lower Zone		
	Shut-In		Shut-In	Flow Test	
	Casing	Tubing	Tubing	Tubing	Flow Rate
9-15	190	--	190		
9-16	195	--	198		
9-17	199	--	202		
9-18	176	--		176	50
9-19	135	--		138	23

Remarks:

Return all correspondence to-El Paso Natural Gas Company
P. O. Box 990
Farmington, New Mexico 87401



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Operator notified to repair

APPROVED 10-1 19 75
NEW MEXICO OIL CONSERVATION COMMISSION

BY _____

OPERATOR Northwest Production Corp.

BY Amy W. Bink

TITLE Well Test Engineer

DATE 9/23/75

DAYS

2 3 4 5

Both Zones
shut in

Pressure
P_{wf}

MV
Flowing

Northwest Production Corp.
Annual Packer Leakage Test 1975
Blanco 32-12 #1 (FM)
Unit A Sec. 4-30-12
San Juan Co., New Mexico

°FT Zone °MV Zone

