



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 99867-A  
Unit Lunt

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 6, 1961, 19

Well No. 61 is located 1120 ft. from N line and 890 ft. from E line of sec. 6

NE 1/4 Sec. 6 (1/4 Sec. and Sec. No.) 20 N (Twp.) 13 W (Range) 18 N (Meridian)  
Dakota (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5640 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 12 3/4" hole to 236' and set 8 5/8" casing to TD with 200 sacks cement.  
Drilled 7 7/8" hole, with mud, to 6355 and set 4 1/2" X 11.60# casing to 6350'  
with 300 sacks. 100 at 6350', 100 sacks at 5580' and 100 sacks at 4250'.  
Perforated Dakota formation and sand-water freed.  
2 3/8" tubing at 6290'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company R & G Drilling Company, Inc.  
Address Box 327  
Farmington, N. M.

By William C. Russell  
Title President