

(SUBMIT IN TRIPLICATE)

Indian Agency San Jose

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 11-28-401-2001

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 11, 1958


Well No. 4-1 is located 1530 ft. from N line and 300 ft. from E line of sec. 9
SE; NE; Sec 9 T 30 N R 17 W RMN
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 9044.2 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 7-17-58 Drilled 7" hole to 105' Ran 3 jts 7" 20# 1-55 csg set @ 90' RIB cemented w/25 wt cement. Drilled 6 1/2" hole to 1042'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company King Oil Company
 Address Val R. Brown & Assoc., Inc.
120 S. Commercial
Farmington, New Mexico
 By _____
 Title Consulting Engineer