

(SUBMIT IN TRIPLICATE)

Indian Agency

Morongo Tribal Com.

X		

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee

Lease No. **14-20-000-733**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 20, 19 **59**

Morongo Morajo

Well No. **1** is located **600** ft. from **N** line and **1900** ft. from **E** line of sec. **5**

NE 1/4 Section 5

(1/4 Sec. and Sec. No.)

30N

16W

NMSPM

(Twp.)

(Range)

(Meridian)

Morongo Gallup Nat.

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is **5350** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

8-26-59 Total Depth 1237'.

Ran 40 joints 5-1/2", 15.500, J-55 Casing (1235') set at 1231.0' with 25 sacks regular cement, 20 sacks Pozmix, 4% gel., 1/40 Flocote per sack.

Held 10000/20 Minutes.

Top of cement by temperature survey at 700'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Products Company**

Address **Post Office Box 1845**


Farmington, New Mexico

ORIGINAL SIGNED BY: **JOSEPH E. KREGER**

By

Title

Petroleum Engineer



RECEIVED BY JOSEPH E. KREGER