


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Navajo
Allotted 20 cubic yds
Lease No. 24-00-000-1000



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 26, 1960

Well No. 2 is located 660 ft. from N line and 2000 ft. from E line of sec. 1
24 Section 1 30N 10W 109W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Navajo Oilfield San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 9000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We wish to report the running and cementing of surface casing.

1. Drilled 24 1/4" hole to 215'.
2. Run 215' 9 5/8" OD 147 5-75 EUE casing and set at 215' with float collar.
3. Cemented with 75 sacks regular cement and 35 bags. Plug down 2/27/60. Circulated cement to surface.
4. Test 24 hrs. Pressure tested OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Navajo Oil Transmission Company
Address P. O. Box 2724
Durango, Colorado
By R. E. Walker R. E. Walker
Title District Production Superintendent