

Santa Fe, New Mexico

Mail to District Office, Oil Conservation Commission, to which Form C-101 was sent not later than twenty days after completion of well. Follow instructions in Rules and Regulations of the Commission. Submit in **QUINTUPLICATE**. If State Land submit 6 Copies

Burroughs State

(Company or Operator)

(Leave)

Well No. **2**, in **NE** $\frac{1}{4}$ of **NW** $\frac{1}{4}$, of Sec. **2**, T. **30N**, R. **16W**, NMPM.

Horseshoe Gallup

San Juan

Pool, County.

Well is 660 feet from North line and 1980 feet from West line.

of Section 2 If State Land the Oil and Gas Lease No. is E-3150-4

Drilling Commenced..... **February 24**, 19 **61** Drilling was Completed..... **March 1**, 19 **61**

Name of Drilling Contractor..... **Banner Drilling Company**

Address Farmington, New Mexico

Elevation above sea level at Top of Tubing Head..... 5659' The information given is to be kept confidential until

No. 1, from 1587' to 1621' No. 4, from _____ to _____

No. 2, from.....to..... No. 5, from.....to.....

No. 3, from.....to..... No. 6, from.....to.....

No. 3, from.....to..... No. 6, from.....to.....

Include data on rate of water inflow and elevation to which water rose in hole.

No. 1. from to feet.

No. 2, from.....to.....feet.

No. 3, from.....to.....feet.

No. 4, from to feet.

SIZE	WEIGHT PER FOOT	NEW OR USED	AMOUNT	KIND OF SHOE	CUT AND PULLED FROM	PERFORATIONS	PURPOSE
9-5/8"	36.00#	New	96'	Texas Pat.			Surface
5-1/2"	15.50#	Used	1684	Texas Pat.		1587'-1621'	Production

SIZE OF HOLE	SIZE OF CASING	WHERE SET	NO. SACKS OF CEMENT	METHOD USED	MUD GRAVITY	AMOUNT OF MUD USED
12-1/4	9-5/8"	102	100	Pump-Plug		
7-7/8	5-1/2"	1692	100	Pump-Plug		

(Record the Process used, No. of Qts. or Gals. used, interval treated or shot.)

Sandoll Fracture interval 1587'-1621' with 36,200 gals. lease crude and 42,000# (10-20) sand.

Flush with 1680 gals. crude. Spotted 250 gals. 7-1/2% MCA ahead of frac.

Result of Production Stimulation.....

Depth Cleaned Out.....1658'

RECEIVED

MAY 17 1961

1658