



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____
Allottee _____
Lease No. _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED
OCT 23 1958
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 10, 1958

Well No. 3 is located **300** ft. from **[N]** line and **1600** ft. from **[E]** line of sec. **8**

Section 3 (Of Sec. and Sec. No.) **300** (Foot) **1600** (Range) **100N** (Meridian)

Section 3 (Field) **San Juan** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is **5322** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

10-4-58 Set 2" 15.30 3-45 in casing at 1940' w/100 cc. cement encasing in gal and 1 1/2 in. flow seal.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **WIND-ONE-22, INC.**

Address **720 E. 10th**
FARMINGTON, NEW MEXICO

By **H. B. GOVE**
Title **MANAGER**

ORIGINAL SIGNED BY
H. B. GOVE

RECEIVED

