

COPY FOR  
STATE OF NEW MEXICO  
OIL CONSERVATION  
COMMISSION  
SUBMIT IN TRIPLICATE TO  
DISTRICT OFFICE

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 079037  
Unit Hale #3

RECEIVED

AUG 14 1952

OIL CON. COM.  
DIST 3

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 13, 1952

Well No. 3 Hale is located 1750 ft. from XX line and 1650 ft. from W line of sec. 34

NE  $\frac{1}{4}$  SW  $\frac{1}{4}$  Sec. 34  
(14 Sec. and Sec. No.)

31 North 8 West  
(Twp.) (Range)

N.M.P.M.  
(Meridian)

Blanco-LaPlata  
(Field)

San Juan County  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 6237 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

Well was spudded August 9, 1952. 9-5/8" cmt. 204' w/125 sx.  
Tested for 30 minutes with 500# pressure with no leaks.  
Cement plug was drilled August 11, 1952, tested for 30 minutes  
with 500# pressure with no drop in pressure.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SOUTHERN UNION GAS COMPANY

Address Box 8156

Farmington, New Mexico

By [Signature]

Title Drilling Supt.