



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078387-A
Unit Kernaghan

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<u>Water Free</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

AUG 10 1961

Well No. 2 is located 1510 ft. from N line and 1190 ft. from E line of sec. 28
NE 1/4 Sec. 28 (1/4 Sec. and Sec. No.) 31N (Twp.) 9W (Range) N.M.P.M. (Meridian)
Blanco Mesa Verde (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6334 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

8-3-61 Total depth 5605'. C.O.T.D. 5585'. Water fractured Point Lookout perf. int. 5460-68; 5473-81; 5498-5506; 5512-20; 5526-34; 5565-73 w/55,000 gallons water and 60,000# sand. ED pr. 600#, max. pr. 4000#, avg. tr. pr. 3000#. I.R. 35 BPM. Flush 4200 gallons.

Set temporary bridge plug at 5400' washed Cliff House perf. int. 5322-5310; 5136-5124; 5116-04 with 500 gallons acid.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 990

Farmington, New Mexico

By Original Signed R. G. MILLER

Title Petroleum Engineer