

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Phillips Petroleum Company

3. Address and Telephone No
5525 Hwy. 64, NBU 3004, Farmington, NM 87401 (505) 599-3454

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit M, 990' FSL & 990' FWL
Section 21, T-31-N, R-8-W

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
SF-079029

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation
San Juan 32-8 Unit

8. Well Name and No.
San Juan 32-8 Unit #12

9. API Well No.
30-045-10460

10. Field and Pool, or Exploratory Area
Blanco Mesaverde

11. County or Parish, State
San Juan, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
☐ Notice of Intent	☐ Abandonment
☒ Subsequent Report	☐ Recompletion
☐ Final Abandonment Notice	☐ Plugging Back
	☐ Casing Repair
	☐ Altering Casing
	☒ Other Pit Closure
	☐ Change of Plans
	☐ New Construction
	☐ Non-Routine Fracturing
	☐ Water Shut-Off
	☐ Conversion to Injection
	☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The pit associated with the subject well's separator and dehydrator has been closed and replaced with a double bottom steel tank. Details of the closure are attached.

Ed Hasely
DISTRICT OIL & GAS INSPECTOR

MAY 31 1993

RECEIVED
MAY - 1 1993

OIL CON. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct

Signed Ed Hasely Ed Hasely

Title Environmental/Regulatory Engineer

(This space for Federal or State office use)

Approved by
Conditions of approval, if any:

Title

MAY 13 1993

DISTRICT MANAGER

PIT REMEDIATION AND CLOSURE REPORT

Operator: Phillips Petroleum Company Telephone: 505-334-3400
Address: 5525 Hwy 64, NBU 3004, Farmington, NM 87401
Facility Or: San Juan 32-8 #12
Well Name _____
Location: Unit or Qtr/Qtr Sec SW SW Sec 21 T 31N R 8W County San Juan
Pit Type: Separator ☒ Dehydrator ☒ Other _____
Land Type: BLM ☒ State _____ Fee _____ Other _____

Pit Location: Pit dimensions: Length 28' width 28' depth 3'
(Attach diagram)
Reference: wellhead ☒ other _____
Footage from reference: 60
Direction from reference: 3 Degrees ☒ East North _____
of
West South ☒

Depth to Ground Water: 310'
(vertical distance from
contaminants to seasonal
highwater elevation of
ground water)
☒ Less than 50 feet (20 points)
☐ 50 ft to 99 feet (10 points)
☐ Greater than 100 feet (0 points) 0

Wellhead Protection Area:
(less than 200 feet from a private
domestic water source, or: less than
1000 feet from all other water sources)
☒ Yes (20 points)
☐ No (0 points) 0

Distance to Surface Water:
(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches.)
☒ Less than 200 feet (20 points)
☐ 200 feet to 1000 feet (10 points)
☐ Greater than 1000 feet (0 points) 0

RECEIVED
MAY - 1 1995
OIL CON. DIV.
DIST. 3

Date Remediation Started: N/A Dated Completed: _____

Excavation _____ Approx. cubic yards _____

Landfarmed _____ Insitu Bioremediation _____

Other _____

Remediation Method: Onsite _____ Offsite _____

(Check all appropriate sections)

General Description of Remedial Action: N/A

Initial assessment showed soils to be clean 3'

below pit bottom.

Ground Water Encountered: No X Yes _____ Depth _____

Final Pit: Sample location deepest part of pit. Sampled with a backhoe.

Closure Sampling:

(if multiple samples,

attach sample results

and diagram of sample

locations and depths)

Sample depth 3' below pit bottom.

Sample date 6-10-94 Sample time _____

Sample Results

Benzene (ppm) 0.26

Total BTEX (PPM) 29

Field Headspace (ppm) 574

TPH 2316

Ground Water Sample: Yes _____ No X (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETED TO THE BEST OF MY KNOWLEDGE AND BELIEF.

DATE 2/1/95

PRINTED NAME Ed Hasely

SIGNATURE 

and TITLE Environmental Engineer

PHILLIPS PETROLEUM PIT ASSESSMENT/RE-ASSESSMENT SUMMARY
 REVISED DATE JULY 14, 1994

1994

ENVIROTECH, INC.

REVENUE DATE: JULY 19, 1994													EPA METHOD 8020 (PPB)									
PIT NO.	WELL NAME	U - S - T - R	PIT TYPE	RANK SCORE	CLOSURE STANDARD TPH (PPM)	DATE	GROUNDWATER BACKFLOWED 5-6- SEPT DATES	SOIL TYPE	SAMPLE NO.	Organic Vapor Method (PPM)	Total Recoverable Per. Hydro. (PPM)	METHOD 5030 PURGE - AND - TRAP					TOTAL BTEX	STATUS				
												Benzene	Toluene	Ethyl Benzene	Xylene							
PA176	SAN JUAN 32-6, #40 MV	A153208	SEP	0	5000	6-9-94	NO	SM	T1-6	>206	10	0	1560	6020	60410	73600	CLOSE					
PA177	SAN JUAN 32-6, #46 PC	A153208	SEP	0	5000	6-8-94	NO	MS	T1-6	>206	1469	1560	64600	6600	62600	166680	REM ~ 6					
PA178	SAN JUAN 32-6, #50 MV	D283208	SEP	0	5000	6-9-94	NO	SP	T1-6	>262	2476	0	590	284	60600	10644	REM ~ 5					
PA179	SAN JUAN 32-6, #12A DK	E213108	SEP	0	5000	6-9-94	NO	SP	T1-7	28	80						CLOSE					
PA180	SAN JUAN 32-6, #11	G213108	SEP	0	5000	6-9-94	NO	SW	T1-6	>157	210	1140	6600	2400	20460	30600	CLOSE					
PA181	SAN JUAN 32-6, #11A DK	I213108	SEP	0	5000	6-9-94	NO	SW	T1-6	>216	330	0	147	28	47	222	CLOSE					
PA182	SAN JUAN 32-6, #12-21	M213108	SEP	0	5000	6-10-94	NO	SW	T1-6	574	2316	280	1200	4520	23070	29090	REM ~ 6					
PA183	SAN JUAN 31-6, #35	A353108	SEP	0	5000	6-10-94	NO	SW	T1-7	26	66						CLOSE					
PA184	SAN JUAN 31-6, #36 DK	A273108	SEP	20	100	6-10-94	NO	SP	T1-7	2	36						CLOSE					
PA185	SAN JUAN 31-6, #40 DK	H063008	SEP	0	5000	6-10-94	NO	SG	T1-7	1	60						CLOSE					
PA186	SAN JUAN 31-6, #51 DK	K053008	SEP	10	1000	6-13-94	NO	MC	T1-6	1	24						CLOSE					
PA187	SAN JUAN 31-6, #46 DK	B313108	SEP	0	5000	6-13-94	NO	MC	T1-7	62	26						CLOSE					
PA188	SAN JUAN 31-6, #41 DK	L263108	SEP	0	5000	6-13-94	NO	CH	T1-7	128	672	71	660	286	1600	2917	CLOSE					
PA189	SAN JUAN 29-5, #4 MV	L062905	SEP	10	1000	6-13-94	NO	SM	T1-7	0	30						CLOSE					
PA190	SAN JUAN 29-5, #26 MV	K182905	SEP	10	1000	6-13-94	NO	CH	T1-7	>262	62	360	1600	560	12189	14609	CLOSE					
PA191	SAN JUAN 29-5, #25 MV	G182905	SEP	20	100	6-13-94	NO	MS	T1-7	0	30						CLOSE					
PA192	SAN JUAN 29-5, #18-5	K052905	SEP	10	1000	6-13-94	NO	MS	T1-7	185	310	90	36500	3180	3210	45980	CLOSE					
PA193	SAN JUAN 29-5, #46-15	L152905	SEP/PROD	10	1000	6-14-94	NO	SM	T1-4	624	24						REM ~ 6					
PA194	SAN JUAN 29-5, #93	C232905	SEP/PROD	0	5000	6-14-94	NO	SM	T1-6	577	684	1260	16500	6500	90600	117660	REM ~ 6					
PA195	SAN JUAN 29-5, #28-20	M202905	SEP/PROD	0	5000	6-14-94	NO	SM	T1-7	701	1000	0	4890	1290	23270	29450	CLOSE					
PA196	SAN JUAN 32-6, #46 PC	K143208	SEP/PROD	0	5000	6-14-94	NO	CM	T1-6	269	156	31	170	117	1093	1411	CLOSE					
PA197	SAN JUAN 32-6, #46 PC	H143208	SEP/PROD	0	5000	6-14-94	NO	SM	T1-6	622	74	0	110	0	627	1727	CLOSE					
PA198	SAN JUAN 32-7, #56 DK	E173207	SEP	0	5000	6-27-94	NO	SM	T1-7	180	6680	0	106	176	1229	1511	REM ~ 12					
PA199	SAN JUAN 32-7, #72 PC	H333207	SEP/PROD	0	5000	6-27-94	NO	SG	T1-7	683	116	31	1540	500	7390	9451	CLOSE					
PA200	SAN JUAN 32-7, #81 MV	A333207	SEP	10	1000	6-27-94	NO	SW	T1-5	460	74	218	356	359	3130	36648	CLOSE					
PA201	SAN JUAN 32-7, #83 MV	M283207	SEP	0	5000	6-27-94	NO	SP	T1-3	3	10						CLOSE					
PA202	SAN JUAN 32-7, #83 PC	M283207	SEP/PROD	0	5000	6-27-94	NO	SP	T1-3	6	46						CLOSE					

NO

JOB No. 93142
PAGE No. 1 of 1

DATE STARTED: _____
DATE FINISHED: 6/10/94
ENVIRO. SPCLT: DEF CLG
OPERATOR: CIMARRON
ASSISTANT: K.C.

LAND USE: Range-lease SF-079029
SURFACE CONDITIONS: dry - earthen pit - slight staining

CLOSURE STD: 5000

RANKING SCOPE: 0

T1: light gray sand, slightly moist, slight odor

$$1158 \times 2 = 2316 \text{ ppm}$$

passed

recommend excavating
top 3' of pit

TEST HOLE LOGS:

TH#:	SOIL TYPE:	SMPL. TYPE:	OVM. TYPE:	TH#:	SOIL TYPE:	SMPL. TYPE:	OVM. TYPE:	TH#:	SOIL TYPE:	SMPL. TYPE:	OVM. TYPE:	TH#:	SOIL TYPE:	SMPL. TYPE:	OVM. TYPE:
1				1				1				1			
2				2				2				2			
3				3				3				3			
4				4				4				4			
5				5				5				5			
6				6				6				6			
7				7				7				7			
8				8				8				8			
9				9				9				9			
10				10				10				10			
11				11				11				11			
12				12				12				12			
13				13				13				13			
14				14				14				14			
15				15				15				15			
16				16				16				16			
17				17				17				17			
18				18				18				18			
19				19				19				19			
20				20				20				20			
21				21				21				21			
22				22				22				22			
23				23				23				23			
24				24				24				24			
25				25				25				25			
26				26				26				26			
27				27				27				27			
28				28				28				28			
29				29				29				29			
30				30				30				30			
31				31				31				31			
32				32				32				32			
33				33				33				33			
34				34				34				34			
35				35				35				35			
36				36				36				36			
37				37				37				37			
38				38				38				38			
39				39				39				39			
40				40				40				40			

pit bottom

SW GRB 574

TD=6'

SCALE

0

FEET

SITE DIAGRAM

