



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office San Jose

Lease No. 103

Unit 1000

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 103 is located 1000 ft. from S line and 1000 ft. from W line of sec. 10  
10 (1/4 Sec. and Sec. No.) 10 (Twp.) 10 (Range) 10 (Meridian)  
10 (Field) 10 (County or Subdivision) 10 (State or Territory)

The elevation of the derrick floor above sea level is 6500 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilling was started on April 1, 1951, with a 10" bit. The first sand was encountered at 1000 ft. and was a fine sand. The well was drilled to a depth of 1000 ft. and was then abandoned.

Drilling was started on April 1, 1951, with a 10" bit.

The well was drilled to a depth of 1000 ft. and was then abandoned.

The well was drilled to a depth of 1000 ft. and was then abandoned.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San Jose

Address San Jose

By J. F. Carl

Title Geological Engineer