



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. W 03358
Unit Northeast Blondo
Unit Agmt. No. 1, Sec. 929

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REPAIRING OR REPAIR.....	X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

WORKOVER

October 1, 1964

Well No. 58-13 (Dml) is located 925 ft. from N line and 990 ft. from E line of sec. 13
NE 1/4 Sec. 13 315 7W N47W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Basin South Las Pinos Dakota San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6524 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pulled and laid down 1" tubing. Pulled and laid down 2-3/8", 10 rd, non upset tubing. Found inside of 2-3/8" tubing pitted by corrosion; replaced from glass-wrapped, 5360', to surface with new 2-3/8", 3-55, 4.75, EUE tubing. Returned well to production.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Blackwood & Nichols Company

Address P. O. Box 1237

Durango, Colorado

By Delano Loos
Original Signed
by Delano Loos
Title Field Superintendent