

Form C 1041
Revised 7/1/57

~~XXXXXXXXXX~~
Recompletion

Farmington, New Mexico 4/6/60
(Place) (Date)

NW 1/4 SW 1/4

Pool

4/6/60

5901

Name of Prop. Firm. **Mesaverde**

perforations

Super rule

17. 011 75 5 -

Natural Prod. Tests: _____ (15.0 ml) _____ (10.0 ml) _____ (10.0 ml) _____ (10.0 ml) _____ (10.0 ml)

Test After Acid or Fracture Treatment (after recovery to volume of oil equal to volume of load oil used):

boils, oil,	oil water in,	hrs,	min. size

NO. 411 7731 -

Natural Iron: Parts	MB/day; hours flow	Pump Size
100	100	100
200	200	200
300	300	300
400	400	400
500	500	500
600	600	600
700	700	700
800	800	800
900	900	900
1000	1000	1000

Method of testing (light, back pressure, etc.):

Test After Acid or Fracture Treatment: _____ Min/ day; Hours if wet _____

Form Size _____ Method of Testing: _____

... fracture treatment have benefits of reduced costs, reduced risk, water, air, and

Sample:	Lucine	late first new
Location:	Press.	oil run to tank

Oil Transformer _____

El Paso Natural Gas Co.

Remarks. An intermitter was installed to facilitate the removal of liquids from the wellbore. Turned back on production 4/7/60.

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved..... **AUG 8 1960**, 19...

El Paso Natural Gas

Company of (herein)

OIL CONSERVATION COMMISSION

Original Signed Emery C. Arnold

Title _____ Supervisor Dist. # 3

R. C. L. F. 10-20


C. E. Powell Signature

Title **Production Engineer**

Send Communications regarding well DIST

2. Value.

Address.....



STATE OF NEW MEXICO	
OIL CONSERVATION COMMISSION	
AZUL DISTRICT OFFICE	
NUMBER OF COPIES RECEIVED	4
DATE RECEIVED	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRODUCTION OFFICE	
OPERATOR	