


ILLEGIBLE



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Land Office Albuquerque

Lease No. 17 - 078196

Unit 17

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 10-D is located 700 ft. from NE line and 1050 ft. from E line of sec. 12
Section 12 (1/4 Sec. and Sec. No.) T. 30N (Twp.) R. 13E (Range) T. 4N. R. 13E. (Meridian)
Undesignated (Field) New Mexico (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5000 ft. C.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

F.B.I.D. - 7161'
 Sand-water fraced with 1900 lbs. water and 45,000/ sand
 Breakdown pressure - 3000/
 Treating pressure - 3000/
 I.R. - 35.5 bps
 Set 215 lbs., 6920' of 2 3/8" tubing, landed at 6920'
 Shut in for gauge.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Astec Oil & Gas Company

Address Drawer 6 570

Fernington, New Mexico

ORIGINAL SIGNED BY JOE C. SALMON

By Joe C. Salmon

Title District Superintendent