



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. MC 6111
Unit U. S. Hoover #2

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. Hoover #2 Vermington, New Mexico July 1, 1960
Well No. 5 is located 1900 from N line and 1900 ft. from E line of MC 6111
34 1/4 N-1/4 of Section 15 T-30-N R-16-W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Horseshoe Casing San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5484. (ASL)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

As a result of not obtaining oil in commercial quantities, we propose to plug and abandon U. S. Hoover #2 Well No. 5 as follows:

1. Spot 25 sacks cement plug on bottom (approximately 200 ft. of fill-up inside casing) and squeeze with minimum pressure to leave perforations covered with cement.
2. Fill hole with fluid.
3. Run 25 sacks cement down 3-1/2" - 4-5/8" annulus (approximately 110' of fill-up to anchor pipe).
4. Remove well head and surface equipment.
5. Spot 5 sacks cement for surface plug (0-40') and erect dry hole marker.
6. Plug and abandonment by above procedure to permit possible re-entry for future secondary recovery purposes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Tan American Petroleum Corporation

Address P. O. Box 400

Vermington, New Mexico

Attn: L. W. Speer, Jr.

ORIGINAL SIGNED BY
R. M. Bauer, Jr.

By _____

Title Area Engineer