



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico

Lease No. NY 00443

Unit O. J. Hoover "E"

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

O. J. Hoover "E"

Farmington, New Mexico

July 18, 1960

Well No. 5 is located 1980 ft. from {N} line and 1980 ft. from {E} line of sec. 15

SE 1/4 NW 1/4 of Section 15
(1/4 Sec. and Sec. No.)

T-30N
(Twp.)

R-16E
(Range)

N.M.P.M.
(Meridian)

Horseshoe Gallup
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5485 ft. (RDB)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

As a result of not obtaining oil in commercial quantities, O. J. Hoover "E" Well No. 5 was plugged and abandoned on July 14, 1960 as follows.

1. Pulled tubing and rods.
2. Set 25 sacks cement plug in 5-1/2" casing (1528-1703').
3. Filled hole with fluid.
4. Set 25 sacks cement plug in 5-1/2"-8-5/8" annulus and squeezed with 200 psi.
5. Removed well head and surface equipment.
6. Spotted 5 sacks cement for surface plug (0-40') and erected dry hole marker.
7. Plug and abandonment by above procedure to permit possible re-entry for future secondary recovery purpose.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Pan American Petroleum Corporation

Address P. O. Box 480

Farmington, New Mexico

Attn: L. O. Spear, Jr.

ORIGINAL SIGNED BY
R. M. Bauer, Jr.

By

Title Area Engineer

