


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. 03566
Unit Stewart



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED
MAY 8 1956
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

Well No. 5 is located 1050 ft. from S line and 990 ft. from W line of sec. 20
Section 20 (1/4 Sec. and Sec. No.) 3-21 (Twp.) 10- (Range) N-21 (Meridian)
Blanco (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6221 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 3-31-50. Total depth 2045'.
Run 23 joints 7', J-55, 20#, casing (2835') set at 2045' with 125 sacks
regular cement, 125 sacks Formix, 1/4# Flocale/ah. and 2# Gel.
Held 1000# 30 minutes.
Top of cement by temperature survey at 1520'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be conducted.

Company El Paso Natural Gas Company

Address Box 997
Farmington, New Mexico

By D. L. Stewart
Title Petroleum Engineer

RECEIVED
U.S. DEPARTMENT OF THE ARMY
WASHINGTON, D.C. 20315
JAN 10 1964

