

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.5. LEASE DESIGNATION AND SERIAL NO.
14-20-0603-8492

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo Tribe

7. UNIT AGREEMENT NAME

N/A

8. FARM OR LEASE NAME

Shiprock

9. WELL NO.

#7

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., E., M., OR BLK. AND
SURVEY OR AREA

14-T30N-R18W

12. COUNTY OR PARISH

San Juan

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ *Contractor: A-Plus Well Service, Inc.*

2. NAME OF OPERATOR

Westgas

3. ADDRESS OF OPERATOR

3107 Bloomfield Highway
P.O. Box 1079 Farmington, NM 874994. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

990' FNL & 2310' FWL

Section 14-T30N-R18W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

This well was plugged and abandoned 8-23-94.

8-23-94

Rig up A-Plus Well Service cementing equipment and lay line to wellhead. Well had
100# pressure. Blow down well and establish rate down 2-7/8" casing into Gallup
formation 1 bpm @ 500#.Plug #1: Mix and pumped 21 sxs 15.6# Class B cement down 2-7/8" casing. Shut in well.
WOC. Cement at surface. Cut wellhead off 5' below surface. Weld on P&A marker (underground
plate). Backfill pit and clean up location.

Steve Mason and Kevin Schneider w/BLM witnessed operations.

RECEIVED
SEP - 7 1994OIL CON. DIV.
DIST. 3

A-Plus Well Service, Inc. BLM Contract 14226910-C4-2005

18. I hereby certify that the foregoing is true and correct

SIGNED *William F. Clark*

TITLE President

DATE 8-31-94

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side

FOR RECORD
SEP 4 1994
FARMINGTON DISTRICT OFFICE