

TABULATION OF DEVIATION TESTS

PAN AMERICAN PETROLEUM CORPORATION

LIKINS GAS COM "A" NO. 4

<u>DEPTH</u>	<u>DEVIATION</u>
100'	1°
189'	1°
577'	1°
941'	1°
1290'	1/2°
1410'	1/2°
1613'	3/4°
2022'	3/4°
2172'	1°
2510'	1°



A F F I D A V I T

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation test taken on PAN AMERICAN PETROLEUM CORPORATION'S Likins Gas Com "A" No. 4, Blanco Pictured Cliffs Field, located in the NW/4 SW/4 of Section 34, T-30-N, R-9-W, San Juan County, New Mexico.

Signed G. W. Eaton, Jr.
Title Area Engineer

NEW MEXICO
THE STATE OF ~~NEW MEXICO~~
San Juan) SS.
COUNTY OF ~~BERNARD~~)

BEFORE ME, the undersigned authority, on this day personally appeared G. W. Eaton, Jr. known to me to be Area Engineer for Pan American Petroleum Corporation and to be the person whose name is subscribed to the above statement, who, being by me duly sworn on oath, states that he has knowledge of the facts stated herein and that said statement is true and correct.

SUBSCRIBED AND SWORN TO before me, a Notary Public in and for said County and State this 22nd day of January, 1968.

Harvey S. Jones (Notary)
Notary Public

My Commission Expires: 22 Jan 1970