Form (May		

REPAIR WELL

(Other)

UNITED STATES

SUBMIT IN TRIPLICATE*

Form approved.

	DEPARTMENT OF THE INTERIOR (Other Instructions on re- GEOLOGICAL SURVEY	5. LEASE DESIGNATION AND SERIAL NO. SF 078201
	SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	OIL X GAS WELL OTHER	7. UNIT AGREEMENT NAME
2.	NAME OF OPERATOR	8. FARM OR LEASE NAME
	El Paso Natural Gas Company	Riddle A
3.		9. WELL NO.
	PO Box 990, Farmington, NM 87401	7 (P&A)
	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1840'N, 1840'E	Undes. Farmington 11. SEC., T., E., M., OR BLK. AND SURVEY OR ABEA
		Sec. 15, T-30-N, R-9-W NMPM
14.	PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or C	San Juan New Mexico
	Check Appropriate box to indicate Nature of Notice, Report, of V	Officer Data
NOTICE OF INTENTION TO: SUBSEQU		UENT REPORT OF:
	TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL
	FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CASING
	8HOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING	ABANDONMENT* X

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

(Other) _

Spotted three 50 sk. cement plugs (total 150 sks.) on bottom to cover to approximately 1800'.

Perforated squeeze holes at 950', mixed 75 sk. cement plug displaced down 4 1 Displaced 40 sks. out perfs, left 35 sks. inside casing.

Mixed 75 sks. cement, pumped down the bradenhead annulus.

CHANGE PLANS

Installed Plug & Abandoned marker with 15 sk. cement surface plug.

(An additional subsequent report will be filed after location has been cleaned and

RECEIVED

MAR 1 4 1972

U. S. GEOLOGICAL SURVEY FARMINGTON, N. M. 18. I hereby certify that the foregoing in the pand correct Original Signed F. H. W. Weband correct March 14, 1972 Petroleum Engineer TITLE (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY: