TABULATION OF DEVIATION TESTS

PAN AMERICAN PETROLEUM CORPORATION

DEPTH		DEVIATION
120'		1/4°
356'	•	1°
855 '	•	1/2°
1375'		1°
1675 '		1°
1759 '		1°
. 2639 '		1/4°
2845 ¹		3/4°
3464 '	•	1/4°
3925 '		1/4°
4247 †		1/4°
4459		1/4°
4680 '		1°
4906 '		1°
5225 '		1°
5718 '	• •	3/4°
6535 '	•	1/4°
7165'		. 3/4°
	•	



AFFIDAVII

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation test taken on PAN AMERICAN PETROLEUM CORPORATION'S W. H. Riddle No. 3, located 1190' FSL & 930' FWL Section 24, T-30-N, R-10-W, San Juan County, New Mexico.

Signed Matan A.
Title Frea Engineer

COUNTY OF	of new mexico) SS. SAN THAN	
	, , , , , , , , , , , , , , , , , , ,	
	the undersigned authority,	
appeared	G. W. Eaton, Jr.	known to me to be Area
Ingineer	for Pan American Petroleum	Corporation and to be the
person who	se name is subscribed to the	ne above statement, who, being he has knowledge of the facts
SUBSCRIBED	AND SWORN TO before me. a	Notary Public in and for said
County and	State this 16 day	of <u>October</u> , 19 69.
•		

Nanny Vaine (tros (4orh)
Notary Public

My Commission Expires: 8: 20-1970