

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SP 669217

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Atlantic B

9. WELL NO.

10

10. FIELD AND POOL, OR WILDCAT

Undesignated F. C.

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 5, T-30-N, R-10-W  
N.M.P.M.

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

1. OIL ☐ GAS ☐ OTHER ☒  
WELL WELL

2. NAME OF OPERATOR

El Paso Natural Gas Company

3. ADDRESS OF OPERATOR

Box 990, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1750'N, 790'E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6264' CL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒

FRACTURE TREATMENT ☒

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

On 11-26-69 spudded well, drilled surface hole and ran 4 joints 5 7/8", 24#, K-55 casing (129') set at 142' w/85 sacks of cement circulated to surface. W.O.C. 12 hours, held 600#/30 Min.

On 12-2-69 T.B. 3102'. Ran 99 joints 2 7/8", 6.4#, J-55 casing (3092') set at 3102' w/250 sacks of cement. W.O.C. until completion.

On 12-4-69 A.B.T.D. 3092'. Perf. 2940-56' w/2 SIF; 3016-24' w/4 SIF. Frac w/30,000 10/20 sand, 33,010 gal. water, dropped 1 set of 32 balls, flushed w/750 gal. water.

RECEIVED

DEC 9 1969

GEOLOGICAL SURVEY



18. I hereby certify that the foregoing is true and correct

SIGNED Original Signed F. H. WOOD

TITLE Petroleum Engineer

DATE 12-8-69

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE