

Oil / Gas / Mining

Val R. Reese, C.P.G.

Geological Consultant
900 Bank of New Mexico Building
Albuquerque, New Mexico 87101

Office: Phone 243-0665
Home: Phone 255-9749

October 5, 1970

Mr. Emery C. Arnold
New Mexico Oil Conservation Commission
1000 Rio Brazos Road
Aztec, New Mexico 87410

Dear Sir:

In compliance with the Oil Conservation Commission Rule No. 111, straight hole deviation tests were made on the Rijan No. 11 well located 2475' from the north line and 660' from the west line in Section 31, Township 30 North, Range 16 West, NMPM, San Juan County, New Mexico, as follows:

350'	1/4°
660'	1/2°
815'	1/4°

Total depth of the well is 895'.

Sincerely,

Val R. Reese
VAL R. REESE

VRR:mb

STATE OF NEW MEXICO
COUNTY OF BERNALILLO

Subscribed and sworn to before me this 5th day of October, 1970.

Mari Lynn Quatrig
Notary Public

My commission expires 9/25/73.

