

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	2
LAND OFFICE	1
OPERATOR	1

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Southern Union Production Company	8. Farm or Lease Name Lester
3. Address of Operator P. O. Box 808, Farmington, New Mexico 87401	9. Well No. 1
4. Location of Well UNIT LETTER <u>H</u> , <u>1670</u> FEET FROM THE <u>North</u> LINE AND <u>1010</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>30 North</u> RANGE <u>11 West</u> N.M.P.M.	10. Field and Pool, or Wildcat Aztec Pictured Cliffs Blanco Mesavende
15. Elevation (Show whether DF, RT, GR, etc.) 5760 ft. R.K.B.	12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spudded 12-1/4" surface hole on December 13, 1974. Drilled to T.D. of 301 Ft. R.K.B.
2. Ran 7 joints of 8-5/8", 24.0#, surface casing. Landed at 300 ft. R.K.B. Cemented casing to surface with 185 sacks cement. Plug down at 1:00 P.M., 12-15-74.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dan R. Collier Original signed by Dan R. Collier TITLE Office Manager DATE 1-21-75  
APPROVED BY [Signature] TITLE SUPERVISOR DIST. #3 DATE 1-23-75  
CONDITIONS OF APPROVAL, IF ANY: